General Environmental Incident Summary

Incident: 3441 Date/Time Notice: 8/29/2014 1841 DEM Incident No:

Responsible Party: ONEOK Rockies Midstream

Date Incident: 8/29/2014 Time Incident: 1220 Duration: 0.1 minutes

County: Williams Twp: 153 Rng: 102 Sec: 10 Qtr: SW SE

Lat: 48.08491 Long: -103.78910 Method: Navigation quality GPS

Location Description: Judson Compressor Station

4614Hwy 1804WillistonND58801

Submitted By: Kim Rudningen Affiliation:

Address: 2700 Lincoln Ave SE

City: Sidney State: MT Zip: 59270

Received By:

Contact Person: Kim Rudningen

2700 LiconIn Ave SE Sidney, MT 59270

Distance Nearest Occupied Building: 1000 Feet Release Contained: Yes

Type of Incident: Condensate release from flare

Description of Released Contaminant: Natural gas condensates/slop water

Volume Spilled: 4.00 barrels Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

Due to liquids building up in the inlet, when the operator when to blow down one of the units, the liquids got into the flare line and were release through the flare tip.

Risk Evaluation:

There are no immediate risks or health hazards associated with this release.

of Fatalities: # of Injuries: Affected Medium: 03 - soil

Potential Environmental Impacts:

There are no effects to surface water. The impact remains on the vegetation and soil just south of the Judson compressor station. There are no other adverse effects expected from this release.

Action Taken or Planned:

The blowdown was immediately stopped. Approximately 4 barrels of condensate sprayed out of the flare tip and was carried by the wind south over the road and a was deposited onto a grassy area approximately 50ft wide and 75 yards long. A cleanup crew has been contacted and the contaminated area will be scraped to remove all contaminated dirt and vegetation. Confirmation samples will be taken to confirm that all of the contaminated materials have been removed.

Wastes Disposal Location: The wastes will be disposed of in a permitted landfill.

Agencies Involved:

Updates

Date: 9/15/2014 Status: Inspected Author: Martin, Russell

Updated Volume:

Notes:

9/15/2014 at 17:45, on location. Impacted area south of the flare stack outside of the facility fence has been scraped. No visible staining on vegetation outside of scraped area. Outer fence line around the entire industrial park, enclosing the compressor station as well, does not have any visible staining to the south and southwest.

Date: 9/2/2014 Status: Reviewed; Followup Required Author: Martin, Russell

Updated Volume:

Notes:

Release from flare at compressor station. Followup is necessary.